SUGGESTED FLOAT SWITCH POSITIONS



Notes:
1.) Measurements are suggested.
Adjust based on wet well depth.
2.) For simplex systems, move the
Lead float to the Lag float position.
Delete the Lag Float.

FabPro systems FabPro Systems ©2026 All Rights Reserved | 868 Sussex Blvd. Broomall, PA 19008. | www.fabprosystems.com